

Related IC: PS3109 (SATA III)

Firmware Change History Description

S9FM01.7→S9FM02.1	Date: 2015/4/27
Description	
<ul style="list-style-type: none">• Add: Vendor Command. (S9FM01.7)• Add: new flash mode. (S9FM01.7)• Add: Support Micron flash. (S9FM01.7)• Mod: Micron flash bad block boundary. (S9FM01.8)• Support: Toshiba 4plane flash. (S9FM01.8)• Mod: System Info data. (S9FM01.9)• Add: Codes for debugging. (S9FM01.9)• Support: Toshiba 24nm SLC 16k NAND. (S9FM01.9)• Fix: DLMC & Power cycling bug. (S9FM02.0)• Support: Toshiba 15nm NAND. (S9FM02.0)• Add: Smart ID for customer. (S9FM02.1)• Mod: Enhance error handling process for special case. (S9FM02.1)	